RADIATOR FAN LOG




2016 APR 4 ⚠

1st APM fan motor replacement (due to Genting overheating?)

2016 OCT 15

APM motor first time, because Genting Oberheat?







2018 JAN 3 ⚠

Minor accident; ground wire came loose maybe?

2018 JAN 10

Radiator fan stopped working; stranded on road













2018 MAR 13

Hit rear boot; stranded around Sunway & Taman Megah (changed fan switch next day)





2018 JUL 11

Stranded at Glenmarie BHP station





2018 JUL 21

Yumcha with Weng; diagnosed how fan switch grounding works







2018 JUL 29

Fan switch R2, replaced at Amansiara workshop








2020 JAN 18


Fan switch R3, Proton Original

2020 JAN 20

Replaced fan switch V4 myself














2020 DEC 21

Fan motor APM by Amansiara workshop


2021 JUN 21


Fan stopped working again; replaced fan socket













2021 JUL 20

Changed relay, still not working (Amansiara)

2021 JUL 25

Bypass switch, direct power, fan still not spinning.





2021 SEPT 18

Stripped wire cover; found loose connection that caused fan to stop working

2021 SEPT 25

Bypassed grounding — fan finally working!

