

WATER LEAK LOG



2007 (ORIGINAL)



2008
2009
2010
2011
2012
2013

2014 (SEPT)
CHECKED WATER LEAKS



2015 (MAR)

REPLACE TAIL LIGHT (TRUNK LEAKS)



2016
2017
2018

2019 (MAY)
REPLACED BOOT RUBBER



2019 (OCT)

DISCOVERED REAR BODY CRACK



2020 (NOV)
REPAIRED REAR BOOT RUST




2021 (MAR)

WATER LEAK TEST WITH DINO



2021 (MAY)
CHECKED LEAKS & DRIED BOOT BOARD



2021 (OCT)
REMOVED REAR SEATS & BUMPER



2023 (MAR)

CONFIRMED BODY SEAM CRACKS



2024 (NOV)
REPLACED REAR BOOT RUBBER SEAL



2024 (NOV)

REPLACED TAIL LAMPS



2025 (APR)
FOUND LEAK (RIGHT SIDE)




2025 (MAY)
TAPED REAR BOOT SEAM / GAP



2025 (NOV)
REAR BOOT & FLOOR LEAK; PLACED DEHUMIDIFIER



2025 (NOV)
SEALED / GLUED REAR SEAT SEAM CRACK



2025 (DEC)
SEALED REAR BOOT HOLE LEAKS



2025 (DEC)
REMOVED REAR SEATS & DRIED CARPET



2026 (AUG 3)
REPLACED REAR WINDSCREEN & SEALED BODY CRACK LINE



FIXED!!

it concludes the entire multi-year troubleshooting arc smoothly!