

WHEEL BEARING LOG




2007 (ORIGINAL)

2008

2009

2010



2011 (OCT 15)

REAR X2 BEARING

RM 386

DAMANSARA JAYA
(INC. TIMING KIT & WATER PUMP SERVICE)



2012

2013 (MAY 20)

FRONT X2 BEARING

TOTAL RM360

PRESS BEARING LABOUR: RM60
(KELANA JAYA)



2014 (JUN 13)

REAR X2 BEARING



RM110X2=220



2015 (MARCH 23)

REAR LEFT BEARING

TOTAL RM110





2016 (FEBRUARY 04)

REAR RIGHT BEARING

+BRAKE CALIPER SERVICE



TOTAL RM287 (KOTA DAMANSARA)



2016 (NOVEMBER 25)

REAR LEFT BEARING

TOTAL RM100



2017

2018

2019 (JULY 11)

REAR X2 BEARING

TOTAL RM170 (AMANSIARA)



2020 (MARCH 7)

REAR X2 BEARING &
LONG SCREWS

254,537KM

BEARING 2XPC RM170

LONG SCREW RM80



2021 (APR 20)

REAR LEFT BEARING

240,643KM

RM85X1 (FIX PRICE)



2023 (MARCH 14)

REAR LEFT BEARING

254,537KM

BEARING RM75

LABOUR RM45



2025 (MAY 16)

REAR LEFT BEARING

292,032KM

RM100

No	: J/0 - 20115
Id	: 792031
Id	: 1
SO	WORK
PCS	100.00
Amount	100.00
Sub Total	100.00
Other Charge	0.00
(Discount)	0.00
Total (MYR)	100.00

